



# Preservation Estimate

**History Walks LLC**  
2636 Washington Street  
Omaha, NE 68107  
(816) 616-9162  
historywalksnebraska.com



## Suggested Preservation

This monument has been broken off at the base. To repair it, we will clean the surface and use stone grade epoxy to reattach the monument to the base. Before doing so, we will unearth the base and set it properly so the monument will be level once reset. We will also clean this monument as it does have some lichen and dirt on the stone.

## Condition

**Level:** Base needs unearthed and reset

**Monument**

**Postion 1:** \_\_\_\_\_

**Monument**

**Postion 2:** \_\_\_\_\_

**Piece Secure** 2 piece reattach

**Soiled (1 - 3)** 2

## Cost

**Cleaning** \$12.50

**Level:** \$25

**Repair:** \$25

**TOTAL: \$62.50**

*Fees are billed in quarter hour increments at a rate of \$25 per hour for cleaning and \$50 per hour for preservation*

## Cemetery Information

**Name:** Emmanuel Evangelical Cemetery

**Address:** 334th St and Church Road

**City, State:** Louisville, NE

**Zip:** \_\_\_\_\_ **County:** Cass

## Client Contact

**Contact Name:** Save a Grave

**Phone:** \_\_\_\_\_

**Email:** \_\_\_\_\_

## Grave Information

**Name:** Anne Dehning

**Birth:** Feb 1880 **Section:** \_\_\_\_\_

**Death:** Aug 1880 **Row/Grave:** \_\_\_\_\_

## Monument

**Type:** Tablet

**Style:** \_\_\_\_\_

**Material/Color:** White Marble

**Base Material:** Marble

**Footstone:** \_\_\_\_\_

## Measurements

**Width:** \_\_\_\_\_

**Length:** \_\_\_\_\_

**Height:** \_\_\_\_\_

**Weight:** \_\_\_\_\_

To calculate weight:  $((LxWxH)/1728) \times 150 \text{min } 180 \text{max}$

## Comments